

| | Type | L # | Hits | Search Text | DBs | Time Stamp | Comments | Error Definition | Errors |
|----|------|-----|------|---|--------|------------------|----------|------------------|--------|
| 1 | BRS | L1 | 33 | 600/\$.ccls. and guidewire same instal\$6 same (catheter or tub\$5) | USP AT | 2004/05/14 15:02 | | | 0 |
| 2 | BRS | L2 | 13 | ("3707972" "4291691" "4508533" "4648865" "4953547" "5334160" "5357961" "5620427" "5643227" "5658309" "5766211" "5830189" "6007522").PN. | USP AT | 2004/05/14 14:49 | | | 0 |
| 3 | BRS | L3 | 5 | ("5255690" "5312338" "5454785" "5460185" "5487729").PN. | USP AT | 2004/05/14 14:53 | | | 0 |
| 4 | BRS | L4 | 2 | ("3528406" "4704111").PN. | USP AT | 2004/05/14 14:58 | | | 0 |
| 5 | BRS | L5 | 8 | ("1481981" "4230110" "4235232" "4299421" "4917094" "4957117" "5113872" "5125905").PN. | USP AT | 2004/05/14 14:58 | | | 0 |
| 6 | BRS | L6 | 50 | 606/\$.ccls. and guidewire same instal\$6 same (catheter or tub\$5) | USP AT | 2004/05/14 15:02 | | | 0 |
| 7 | BRS | L7 | 44 | 6 not 1 | USP AT | 2004/05/14 14:59 | | | 0 |
| 8 | BRS | L8 | 67 | 604/\$.ccls. and guidewire same instal\$6 same (catheter or tub\$5) | USP AT | 2004/05/14 15:02 | | | 0 |
| 9 | BRS | L9 | 41 | 600/\$.ccls. and guidewire same instal\$6 and (catheter or tub\$5) | USP AT | 2004/05/14 15:03 | | | 0 |
| 10 | BRS | L10 | 8 | 9 not 1 | USP AT | 2004/05/14 15:03 | | | 0 |
| 11 | BRS | L11 | 77 | 606/\$.ccls. and guidewire same instal\$6 and (catheter or tub\$5) | USP AT | 2004/05/14 15:03 | | | 0 |

| | Type | L # | Hits | Search Text | DBs | Time Stamp | Comments | Error Definition | Errors |
|----|------|-----|------|---|-----------|----------------------|----------|------------------|--------|
| 12 | BRS | L12 | 21 | ("Re30365" "4066070" "4306562" "4323071" "4535773" "4540404" "4616652" "4723550" "4726374" "5158540" "5219329" "5224945" "5318532" "5324306" "5376077" "5397305" "5439447" "5484418" "5505725" "5603698" "5649950").PN. | USP AT | 2004/05/1 4 15:04 | | | 0 |